

SIX SIGMA PROJECT CHARTER - DEFINE

P1

| PROJECT TITLE | | 2300C PRODUCTION LINE SCRAP REDUCTION & SECONDARY EQUIPMENT RELIABILITY IMPROVEMENT | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---------------------------------|--|---------------------------------|------|-----------|----------------------|------------------------|-----------------|---------------------------------|----------------------|--------|-------------|-----------------|----------------------|--------|--------------|-----------------------------|----------------------|---------|------------------|----------------------|----------------------|--------|------------------|---------------------|----------------------|--------|---------------|---------------------|----------------------|--------|--------------------|---------------------|----------------------|--------|---------------|----------------|----------------------|--------|--------------|------------------|----------------------|--------|---------------|--------------------|----------------------|--------|
| BUSINESS IMPACT | | EXPECTED OUTCOMES TARGETED GOALS | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p><i>Why is this problem important to business? How is the problem impacting business results in terms of Safety, Quality, Delivery, Environment? Cost?</i></p> <p>The impact to the business is financial which can be extrapolated to include the cost of loss of profit, recycling costs, disposal cost, rework costs, re-make the and replenishment costs loss of profit etc. The scrap report below was generated from the time period between 01-Jan-20 to 31-Oct-20</p> | | <p><i>What do we want to achieve? How should things work? What actions will address the most important causes? What will be some of benefits to this project?</i></p> <p>We want to make a 50% reduction in scrap parts for those identified part numbers from their current scrap rates. Focus on 2300C as this is the production with the most valuable part that you manufacture. Conduct improvement activities on 6 major product family parts as detailed in the Business Impact and at least once on all the other product family parts within the first of the year 2021. Reduce the number of external quality defective escaping to the customers of these part families MBSUI and BMW by 50% in the first year of project 2021.</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| LH WHL Front/Rear G05 (# 113135604) | 131,644 ◀TOTAL PARTS PRODUCED | 1,680 ◀TOTAL SCRAPPED PARTS | \$4,741 ◀ PART COST LOSS TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| RH WHL Front/Rear G05 (# 113135704) | 128,536 ◀TOTAL PARTS PRODUCED | 2, 683 ◀TOTAL SCRAPPED PARTS | \$7,686 ◀ PART COST LOSS TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Wheelhouse Liner Fr/Fr LH G05 (# 113135403) | 135,190 ◀TOTAL PARTS PRODUCED | 1,751 ◀TOTAL SCRAPPED PARTS | \$5,003 ◀ PART COST LOSS TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Wheelhouse Liner Fr/Fr RH G05 (# 113135503) | 133,159 ◀TOTAL PARTS PRODUCED | 2,783 ◀TOTAL SCRAPPED PARTS | \$8,013 ◀ PART COST LOSS TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| LHD Cowl Grill Center G05/G6/G7 (# 113069403) | 185,933 ◀TOTAL PARTS PRODUCED | 12,581 ◀TOTAL SCRAPPED PARTS | \$12,727 ◀ PART COST LOSS TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Lower Partition Wall LHD G0506 (# 113133905) | 195,744 ◀TOTAL PARTS PRODUCED | 4,679 ◀TOTAL SCRAPPED PARTS | \$8,555 ◀ PART COST LOSS TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Center Partition Wall LHD G0506 (# 113133505) | 187,261 ◀TOTAL PARTS PRODUCED | 8,555 ◀TOTAL SCRAPPED PARTS | \$10,202 ◀ PART COST LOSS TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SCR Tank BR167 Daimler (#112513903) | 54,184 ◀TOTAL PARTS PRODUCED | 2,635 ◀TOTAL SCRAPPED PARTS | \$72,825 ◀ PART COST LOSS TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SCR Tank VS30 Daimler (# 113772901) | 14,854 ◀TOTAL PARTS PRODUCED | 1,226 ◀TOTAL SCRAPPED PARTS | \$24,038 ◀ PART COST LOSS TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| OPPORTUNITY OR PROBLEM STATEMENT | | ACTION ITEMS AND COUNTERMEASURES | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p><i>What is wrong with what? Who is affected? What is known? Why are we talking about this? Customer non-conformance? Performance gaps? Lost Opportunity?</i></p> <p>For the past 10 months the scrap rate for each of the selected parts has been above plan with the following current combined scrap rates have been 01.01.20 - 11.30.20. Baseline numbers:-</p> <ul style="list-style-type: none"> • 2300A BMW G05 LH/RH Rear Section Wheel House Liner = 1.7% scrap • 2300B BMW G05 LH/RH Front Section Wheel House Liner = 1.7% scrap • 1300A BMW G05/G06 LHD Center Partition Wall = 4.4% scrap • 1300A BMW G06/G06 Lower Partition Wall = 2.2% scrap • 2300G BMW G05/G06/G07 Cowl Grill = 6.9% scrap • 2300C Daimler BR167 SCR Tank = 4.9% scrap • 2300C Daimler VS30 SCR Tank = 8.1% scrap • 2300C BMW Gen 3 G05/G06 SCR Tank = 5.5% scrap • 2300C BMW Gen 4 G05/G06 SCR Tank = 5.4% scrap | | <p><i>Who is going to do what by when? Follow up? How will the action items be managed?</i></p> <p>Refer to improvement phase of project charter tabs for specific actions items by department, by person, by date. The action items will be managed by the individual tasks and associated sub-tasks assigned to each department as a breakdown by priority of impact.</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| GOAL STATEMENT | | MEASURES AND METRICS | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p><i>What do we want to achieve? How should things work? What actions will address the most important causes? What will be some of benefits? Expected Outcomes?</i></p> <p>Reduce scrap for selected products in scope by 50% within one year of beginning of project for each of the product families listed in Business Impact with emphasis being on 2300C as this is the most expensive production line for scrap - see Business Impact above.</p> | | <p><i>What will be the long term effectiveness tracking measurements, metrics periods to show the Improvement Case has had affect and no recurrence of the problem?</i></p> <p>For production lines 2300A, 2300B, 1300A, 2300G will be scrap as sum of parts ran minus the sum defective scraped parts. 2300C as it is a multi process production line will use both total scrap and roll throughput yield of the individual work stations as each work station introduces a componant that changes the in process value of the part.</p> <p>The reporting period for project review and acheived milestones will be held weekly with the team members selection below in Team Selection. We will review:-</p> <ul style="list-style-type: none"> • Scrap for the previous calendar week • Equipment related breakdown and basic analysis report taken from JOT • Roll througput yield on a monthly basis • Action items reviews per department | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| PROJECT SCOPE | | TEAM SELECTION | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p><i>What is in-scope to the problem? What if there is more than one problem? What can we get achieved in 3-5 days to get noticeable results?</i></p> <p>The scope of the project will be limited to IMM 2300A PRODUCTION LINE # 3011032 - IMM 2300B PRODUCTION LINE # 3011034 - IMM 1300A PRODUCTION LINE # 3011028 - IMM 2300G PRODUCTION LINE # 3011038 - IMM 2300C PRODUCTION LINE # 3011036 - All process or part families are out of scope with this project.</p> <p>Specific parts:-</p> <p>IMM 2300A - LH WHL Front/Rear G05 (# 113135604) / RH WHL Front/Rear G05 (# 113135704) IMM 2300B - Wheelhouse Liner Fr/Fr LH G05 (# 113135403) / Wheelhouse Liner Fr/Fr RH G05 (# 113135503) IMM 1300A - Lower Partition Wall LHD G0506 (# 113133905) / Center Partition Wall LHD G0506 (# 113133505) IMM 2300G - LHD Cowl Grill Center G05/G06/G07 (# 113069403) IMM 2300C - SCR Tank BR167 Daimler (#112513903) / SCR Tank VS30 Daimler (# 113772901)/SCR Tank Gen 3 G05/G06 BMW (# 113068907)</p> | | <p><i>Who needs to be involved in the project? Operators? Subject matter experts? Vendors? Customers? Independent observers? What will be their roles?</i></p> <table border="1"> <thead> <tr> <th>NAME</th> <th>JOB TITLE</th> <th>DEPARTMENT / COMPANY</th> <th>SIX SIGMA PROJECT ROLE</th> </tr> </thead> <tbody> <tr> <td>Fred Webberking</td> <td>Continuous Improvement Engineer</td> <td>Roechling Automotive</td> <td>Leader</td> </tr> <tr> <td>Brad Turner</td> <td>Process Manager</td> <td>Roechling Automotive</td> <td>Member</td> </tr> <tr> <td>Tim Mittmann</td> <td>Director Project Management</td> <td>Roechling Automotive</td> <td>Sponsor</td> </tr> <tr> <td>Stefan Pardeller</td> <td>Technical Supervisor</td> <td>Roechling Automotive</td> <td>Member</td> </tr> <tr> <td>Jammie Rasmussen</td> <td>Maintenance Manager</td> <td>Roechling Automotive</td> <td>Member</td> </tr> <tr> <td>Keaton Walker</td> <td>Automation Engineer</td> <td>Roechling Automotive</td> <td>Member</td> </tr> <tr> <td>Vladik Zadorozhnyy</td> <td>Automation Engineer</td> <td>Roechling Automotive</td> <td>Member</td> </tr> <tr> <td>Matthew Urias</td> <td>Tooling Manger</td> <td>Roechling Automotive</td> <td>Member</td> </tr> <tr> <td>Rober Kehler</td> <td>Process Engineer</td> <td>Roechling Automotive</td> <td>Member</td> </tr> <tr> <td>Brian Walulik</td> <td>Technical Director</td> <td>Roechling Automotive</td> <td>Member</td> </tr> </tbody> </table> | | NAME | JOB TITLE | DEPARTMENT / COMPANY | SIX SIGMA PROJECT ROLE | Fred Webberking | Continuous Improvement Engineer | Roechling Automotive | Leader | Brad Turner | Process Manager | Roechling Automotive | Member | Tim Mittmann | Director Project Management | Roechling Automotive | Sponsor | Stefan Pardeller | Technical Supervisor | Roechling Automotive | Member | Jammie Rasmussen | Maintenance Manager | Roechling Automotive | Member | Keaton Walker | Automation Engineer | Roechling Automotive | Member | Vladik Zadorozhnyy | Automation Engineer | Roechling Automotive | Member | Matthew Urias | Tooling Manger | Roechling Automotive | Member | Rober Kehler | Process Engineer | Roechling Automotive | Member | Brian Walulik | Technical Director | Roechling Automotive | Member |
| NAME | JOB TITLE | DEPARTMENT / COMPANY | SIX SIGMA PROJECT ROLE | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Fred Webberking | Continuous Improvement Engineer | Roechling Automotive | Leader | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Brad Turner | Process Manager | Roechling Automotive | Member | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Tim Mittmann | Director Project Management | Roechling Automotive | Sponsor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Stefan Pardeller | Technical Supervisor | Roechling Automotive | Member | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Jammie Rasmussen | Maintenance Manager | Roechling Automotive | Member | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Keaton Walker | Automation Engineer | Roechling Automotive | Member | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Vladik Zadorozhnyy | Automation Engineer | Roechling Automotive | Member | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Matthew Urias | Tooling Manger | Roechling Automotive | Member | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Rober Kehler | Process Engineer | Roechling Automotive | Member | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Brian Walulik | Technical Director | Roechling Automotive | Member | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| PROJECT PLAN | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p><i>When are we going to start the project? When would we like to finish the project? What are some of the major milestones? What are the five W's and five M's?</i></p> <p>The project started on September 1st 2020 and projected as a goal to be completed by March 31st 2021 Major milestones will be the acheivement of the targeted scrap reduction goal as a percent % for each of the five (5) products listed in 1. The Who, What, Where, When, How, and How much can found on each of the individual department action item activities for the IMPROVE tabs of this charter. Inside each improve tab covers the resources People, Facilities, Equipment, and Materials that will be needed. Identified project activities with a schedule that includes an estimate of when each activity will take place and what resources are required to finish the tasks the project plan document is expected to change over time as more information about the project becomes available will be seen for each department undertaking their specific plan of action as this is a multi-department resources requiremnts.</p> <p>Parts and machines are: - • 2300A All BMW parts Wheel House Liner • 2300B All Volvo parts Wheel House Liner • 1300A All parts Lower Partition Wall / Center Partitiion Wall • 2300G All parts Cowl Grill BMW • 2300C All parts SCR Tanks BMW MBUSA</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SIX SIGMA PROJECT CHARTER - MEASURE



PROJECT TITLE 2300C PRODUCTION LINE SCRAP REDUCTION & SECONDARY EQUIPMENT RELIABILITY IMPROVEMENT

2300A BASE LINE MEASUREMENT

Have relevant Key Performance Indicators been selected and or developed? Have the KPIs been defined clearly using process maps and operational definitions?

Scrap is measured in several different ways whether measuring internal or external as a metric. Quality as an 'operational definition' is measured as good goods ran against bad parts produced as a percentage or count. Other measures specific to a particular project line use Roll Throughput Yield as in the case of a multi-process production cell such as 2300C which is a production cell that has discrete operations.

- 2300A BMW G05 LH Front Rear Section Wheel House Liner - Total parts ran in 2020 = 166,036 - Total scrapped parts 2020 = 2,185 = 1.3%
- 2300A BMW G05 RH Front Rear Section Wheel House Liner - Total parts ran in 2020 = 166,928 - Total scrapped parts 2020 = 3,234 = 1.9%





ected already available or did you have mine it?

2300B BASE LINE MEASUREMENT

Is the quality of the data been checked challenged using a measurement system analysis such as a gauge repeatability and reproducibility?

- 2300B BMW G05 LH Front Front Section Wheel House Liner - Total parts ran in 2020 = 162,562 - Total scrapped parts 2020 = 1,977 = 1.2%
- 2300B BMW G05 RH Front Front Section Wheel House Liner - Total parts ran in 2020 = 160,255 - Total scrapped parts 2020 = 3,126 = 1.9%





have been selected for the problem and why?

1500B BASE LINE MEASUREMENT

Has the process capability been analyzed if applicable to the problem and the problem goal statement updated if necessary? Does the process look stable?

- 1300A BMW G05/G06 LHD Center Partition Wall - Total parts ran in 2020 = 437,606 - Total scrapped parts 2020 = 20,140 = 4.4%
- 1300A BMW G06/G06 LHD Lower Partition Wall - Total parts ran in 2020 = 447,676 - Total scrapped parts 2020 = 10,070 = 2.2%





ata during Analyze? In what context?

2300G BASE LINE MEASUREMENT

Where is the data and information coming from? Is it reliable and trustworthy? What has been learnt about the historical behavior of the whole process/s?

- 2300G BMW G05/G06/G07 Cowl Grill - Total parts ran in 2020 = 227,717 - Total scrapped part in 2020 = 16,073 = 7.0%





en converted into a Sigma level?

2300C BASE LINE MEASUREMENT

What is the best the process has ever performed and worst? Over what time period was the baseline performance of the process been established?

- 2300C Daimler BR167 SCR Tank Total parts ran in 2020-21 YTD = 63,864 - Total scrapped parts in 2020-21 = 3,275 = 5.1%
- 2300C Daimler VS30 SCR Tank Total parts ran in 2020-21 YTD = 18,727 - Total scrapped parts in 2020-21 = 1,554 = 8.2%
- 2300C BMW Gen 3 G05/G06 SCR Tank Total parts ran in 2020-YTD = 21,624 - Total scrapped parts in 2020-21 = 1,266 = 5.8%
- 2300C BMW Gen 4 G05/G06 SCR Tank Total parts ran in 2020 = 15,104 - Total scrapped parts in 2020-21 = 1,090 = 7.2%
- 2300C Roll Throughput Yield 2021 to date as of 10.08.21 is 84.23% as a measure of long term performance.

- MTBF = 2.9 hrs - MTTR = 1.5 hrs - 41.5 hrs downtime - 42 breakdowns average between survey period of 06.14.21 to 07.26.21
- Conducted a measurement of historical data taken from the data aquisition registry detailing measured failure for both 0040-3017193 Shell to Shell Welder and the 0080-3017195 End Of Line Tester which yielded invaluable information for in process failures which can be view in the EVIDENCE tab of this charter by clicking on the hyperlink 0040-3017193 Production Data. Also the same information for the 0080-3017195 End Of Line Tester click on the hyperlink 0080-3017195 Production Data.



ing historical data and information?

SIX SIGMA PROJECT CHARTER - ANALYZE

P3

PROJECT TITLE 2300C PRODUCTION LINE SCRAP REDUCTION & SECONDARY EQUIPMENT RELIABILITY IMPROVEMENT

2300C

Has if applicable been mapped in detail as it is? Have the selected team gained first hand experience of the product, process, system, equipment or machine?

After reviewing the pareto charts and stack bar charts the major contributor to scrap parts was not actually defects. The injection molding machine on 2300C produces the top and lower SCR tank shells in one cycle as a matched pair. After molding the two parts the top and bottom shells of the tank have components installed on them such as vent tubes and module pumps at discrete work cell station downstream the injection molding process. It was discovered that if the two halves of the SCR tank if allowed to cool to room temperature the parts cannot be processed any further down the production cell from the injection molding process or after discrete operation station 0020 or 0030. If a single discrete operation station were to become unavailable because of a equipment related unplanned breakdown the parts off from the injection molding machine would have to be thrown away if they came down to room temperature. The parts essentially are good, not defective unless they came to room temperature. The amount of parts that were allowed to accumulate when this occurred was not specific. The operators would record the scrapped parts as 'Missing Operation' on the DCDS. 'Missing Operation' and 'Start Up Parts' are the two biggest contributors to defective scrapped parts as seen on the Pareto Chart.


Has designed experiments (DOE) been used where applicable to find the critical process inputs? What are the key roots causes of failures or critical process inputs.

This a downloaded data taken from 0040-3017193 Shell To Shell clearly showing welding force the number one processing error as to why the machine is failing to meet it performance was for torque outs.

| Phase 1 Removed From main | Phase 2 | Phase 3 |
|---------------------------------|---------------|----------------|
| C001 Phase 1 removed from main | C002 Phase 2 | C003 Phase 3 |
| C002 Phase 2 removed from main | C003 Phase 3 | C004 Phase 4 |
| C003 Phase 3 removed from main | C004 Phase 4 | C005 Phase 5 |
| C004 Phase 4 removed from main | C005 Phase 5 | C006 Phase 6 |
| C005 Phase 5 removed from main | C006 Phase 6 | C007 Phase 7 |
| C006 Phase 6 removed from main | C007 Phase 7 | C008 Phase 8 |
| C007 Phase 7 removed from main | C008 Phase 8 | C009 Phase 9 |
| C008 Phase 8 removed from main | C009 Phase 9 | C010 Phase 10 |
| C009 Phase 9 removed from main | C010 Phase 10 | C011 Phase 11 |
| C010 Phase 10 removed from main | C011 Phase 11 | C012 Phase 12 |
| C011 Phase 11 removed from main | C012 Phase 12 | C013 Phase 13 |
| C012 Phase 12 removed from main | C013 Phase 13 | C014 Phase 14 |
| C013 Phase 13 removed from main | C014 Phase 14 | C015 Phase 15 |
| C014 Phase 14 removed from main | C015 Phase 15 | C016 Phase 16 |
| C015 Phase 15 removed from main | C016 Phase 16 | C017 Phase 17 |
| C016 Phase 16 removed from main | C017 Phase 17 | C018 Phase 18 |
| C017 Phase 17 removed from main | C018 Phase 18 | C019 Phase 19 |
| C018 Phase 18 removed from main | C019 Phase 19 | C020 Phase 20 |
| C019 Phase 19 removed from main | C020 Phase 20 | C021 Phase 21 |
| C020 Phase 20 removed from main | C021 Phase 21 | C022 Phase 22 |
| C021 Phase 21 removed from main | C022 Phase 22 | C023 Phase 23 |
| C022 Phase 22 removed from main | C023 Phase 23 | C024 Phase 24 |
| C023 Phase 23 removed from main | C024 Phase 24 | C025 Phase 25 |
| C024 Phase 24 removed from main | C025 Phase 25 | C026 Phase 26 |
| C025 Phase 25 removed from main | C026 Phase 26 | C027 Phase 27 |
| C026 Phase 26 removed from main | C027 Phase 27 | C028 Phase 28 |
| C027 Phase 27 removed from main | C028 Phase 28 | C029 Phase 29 |
| C028 Phase 28 removed from main | C029 Phase 29 | C030 Phase 30 |
| C029 Phase 29 removed from main | C030 Phase 30 | C031 Phase 31 |
| C030 Phase 30 removed from main | C031 Phase 31 | C032 Phase 32 |
| C031 Phase 31 removed from main | C032 Phase 32 | C033 Phase 33 |
| C032 Phase 32 removed from main | C033 Phase 33 | C034 Phase 34 |
| C033 Phase 33 removed from main | C034 Phase 34 | C035 Phase 35 |
| C034 Phase 34 removed from main | C035 Phase 35 | C036 Phase 36 |
| C035 Phase 35 removed from main | C036 Phase 36 | C037 Phase 37 |
| C036 Phase 36 removed from main | C037 Phase 37 | C038 Phase 38 |
| C037 Phase 37 removed from main | C038 Phase 38 | C039 Phase 39 |
| C038 Phase 38 removed from main | C039 Phase 39 | C040 Phase 40 |
| C039 Phase 39 removed from main | C040 Phase 40 | C041 Phase 41 |
| C040 Phase 40 removed from main | C041 Phase 41 | C042 Phase 42 |
| C041 Phase 41 removed from main | C042 Phase 42 | C043 Phase 43 |
| C042 Phase 42 removed from main | C043 Phase 43 | C044 Phase 44 |
| C043 Phase 43 removed from main | C044 Phase 44 | C045 Phase 45 |
| C044 Phase 44 removed from main | C045 Phase 45 | C046 Phase 46 |
| C045 Phase 45 removed from main | C046 Phase 46 | C047 Phase 47 |
| C046 Phase 46 removed from main | C047 Phase 47 | C048 Phase 48 |
| C047 Phase 47 removed from main | C048 Phase 48 | C049 Phase 49 |
| C048 Phase 48 removed from main | C049 Phase 49 | C050 Phase 50 |
| C049 Phase 49 removed from main | C050 Phase 50 | C051 Phase 51 |
| C050 Phase 50 removed from main | C051 Phase 51 | C052 Phase 52 |
| C051 Phase 51 removed from main | C052 Phase 52 | C053 Phase 53 |
| C052 Phase 52 removed from main | C053 Phase 53 | C054 Phase 54 |
| C053 Phase 53 removed from main | C054 Phase 54 | C055 Phase 55 |
| C054 Phase 54 removed from main | C055 Phase 55 | C056 Phase 56 |
| C055 Phase 55 removed from main | C056 Phase 56 | C057 Phase 57 |
| C056 Phase 56 removed from main | C057 Phase 57 | C058 Phase 58 |
| C057 Phase 57 removed from main | C058 Phase 58 | C059 Phase 59 |
| C058 Phase 58 removed from main | C059 Phase 59 | C060 Phase 60 |
| C059 Phase 59 removed from main | C060 Phase 60 | C061 Phase 61 |
| C060 Phase 60 removed from main | C061 Phase 61 | C062 Phase 62 |
| C061 Phase 61 removed from main | C062 Phase 62 | C063 Phase 63 |
| C062 Phase 62 removed from main | C063 Phase 63 | C064 Phase 64 |
| C063 Phase 63 removed from main | C064 Phase 64 | C065 Phase 65 |
| C064 Phase 64 removed from main | C065 Phase 65 | C066 Phase 66 |
| C065 Phase 65 removed from main | C066 Phase 66 | C067 Phase 67 |
| C066 Phase 66 removed from main | C067 Phase 67 | C068 Phase 68 |
| C067 Phase 67 removed from main | C068 Phase 68 | C069 Phase 69 |
| C068 Phase 68 removed from main | C069 Phase 69 | C070 Phase 70 |
| C069 Phase 69 removed from main | C070 Phase 70 | C071 Phase 71 |
| C070 Phase 70 removed from main | C071 Phase 71 | C072 Phase 72 |
| C071 Phase 71 removed from main | C072 Phase 72 | C073 Phase 73 |
| C072 Phase 72 removed from main | C073 Phase 73 | C074 Phase 74 |
| C073 Phase 73 removed from main | C074 Phase 74 | C075 Phase 75 |
| C074 Phase 74 removed from main | C075 Phase 75 | C076 Phase 76 |
| C075 Phase 75 removed from main | C076 Phase 76 | C077 Phase 77 |
| C076 Phase 76 removed from main | C077 Phase 77 | C078 Phase 78 |
| C077 Phase 77 removed from main | C078 Phase 78 | C079 Phase 79 |
| C078 Phase 78 removed from main | C079 Phase 79 | C080 Phase 80 |
| C079 Phase 79 removed from main | C080 Phase 80 | C081 Phase 81 |
| C080 Phase 80 removed from main | C081 Phase 81 | C082 Phase 82 |
| C081 Phase 81 removed from main | C082 Phase 82 | C083 Phase 83 |
| C082 Phase 82 removed from main | C083 Phase 83 | C084 Phase 84 |
| C083 Phase 83 removed from main | C084 Phase 84 | C085 Phase 85 |
| C084 Phase 84 removed from main | C085 Phase 85 | C086 Phase 86 |
| C085 Phase 85 removed from main | C086 Phase 86 | C087 Phase 87 |
| C086 Phase 86 removed from main | C087 Phase 87 | C088 Phase 88 |
| C087 Phase 87 removed from main | C088 Phase 88 | C089 Phase 89 |
| C088 Phase 88 removed from main | C089 Phase 89 | C090 Phase 90 |
| C089 Phase 89 removed from main | C090 Phase 90 | C091 Phase 91 |
| C090 Phase 90 removed from main | C091 Phase 91 | C092 Phase 92 |
| C091 Phase 91 removed from main | C092 Phase 92 | C093 Phase 93 |
| C092 Phase 92 removed from main | C093 Phase 93 | C094 Phase 94 |
| C093 Phase 93 removed from main | C094 Phase 94 | C095 Phase 95 |
| C094 Phase 94 removed from main | C095 Phase 95 | C096 Phase 96 |
| C095 Phase 95 removed from main | C096 Phase 96 | C097 Phase 97 |
| C096 Phase 96 removed from main | C097 Phase 97 | C098 Phase 98 |
| C097 Phase 97 removed from main | C098 Phase 98 | C099 Phase 99 |
| C098 Phase 98 removed from main | C099 Phase 99 | C100 Phase 100 |

Has a Failure Mode Effect Analysis been used if applicable to identify the greatest areas of risk in the product, process, system, equipment or machine?

The maintenance, automation and processing department will need to have a way and means to record unplanned events to capture all and any lost time event to use for analysis for the 'Missing Operations' events. When we have failures every day that occur in a tangled web of difference reasons and different varying causes it is hard if not impossible to determine a recurring pattern that can help us go from the general to the specific. Small almost unnoticed deviations from established standards when left unrepaired or restored their performance reductions can have a cumulative effect that can exceed individual contributions. That



What were your theories about the potential cause/s of the problem when you started the Analyze phase? Were those theories proven during the analysis or not?

This a downloaded data taken from 0080-30171953 End of Line Tester clearly showing welding force the number one processing error as to why the machine is failing to meet it performance was failing to install bushing number 3 for VS30.


| Phase 1 | Phase 2 | Phase 3 |
|---------------------------------|---------------|----------------|
| C001 Phase 1 removed from main | C002 Phase 2 | C003 Phase 3 |
| C002 Phase 2 removed from main | C003 Phase 3 | C004 Phase 4 |
| C003 Phase 3 removed from main | C004 Phase 4 | C005 Phase 5 |
| C004 Phase 4 removed from main | C005 Phase 5 | C006 Phase 6 |
| C005 Phase 5 removed from main | C006 Phase 6 | C007 Phase 7 |
| C006 Phase 6 removed from main | C007 Phase 7 | C008 Phase 8 |
| C007 Phase 7 removed from main | C008 Phase 8 | C009 Phase 9 |
| C008 Phase 8 removed from main | C009 Phase 9 | C010 Phase 10 |
| C009 Phase 9 removed from main | C010 Phase 10 | C011 Phase 11 |
| C010 Phase 10 removed from main | C011 Phase 11 | C012 Phase 12 |
| C011 Phase 11 removed from main | C012 Phase 12 | C013 Phase 13 |
| C012 Phase 12 removed from main | C013 Phase 13 | C014 Phase 14 |
| C013 Phase 13 removed from main | C014 Phase 14 | C015 Phase 15 |
| C014 Phase 14 removed from main | C015 Phase 15 | C016 Phase 16 |
| C015 Phase 15 removed from main | C016 Phase 16 | C017 Phase 17 |
| C016 Phase 16 removed from main | C017 Phase 17 | C018 Phase 18 |
| C017 Phase 17 removed from main | C018 Phase 18 | C019 Phase 19 |
| C018 Phase 18 removed from main | C019 Phase 19 | C020 Phase 20 |
| C019 Phase 19 removed from main | C020 Phase 20 | C021 Phase 21 |
| C020 Phase 20 removed from main | C021 Phase 21 | C022 Phase 22 |
| C021 Phase 21 removed from main | C022 Phase 22 | C023 Phase 23 |
| C022 Phase 22 removed from main | C023 Phase 23 | C024 Phase 24 |
| C023 Phase 23 removed from main | C024 Phase 24 | C025 Phase 25 |
| C024 Phase 24 removed from main | C025 Phase 25 | C026 Phase 26 |
| C025 Phase 25 removed from main | C026 Phase 26 | C027 Phase 27 |
| C026 Phase 26 removed from main | C027 Phase 27 | C028 Phase 28 |
| C027 Phase 27 removed from main | C028 Phase 28 | C029 Phase 29 |
| C028 Phase 28 removed from main | C029 Phase 29 | C030 Phase 30 |
| C029 Phase 29 removed from main | C030 Phase 30 | C031 Phase 31 |
| C030 Phase 30 removed from main | C031 Phase 31 | C032 Phase 32 |
| C031 Phase 31 removed from main | C032 Phase 32 | C033 Phase 33 |
| C032 Phase 32 removed from main | C033 Phase 33 | C034 Phase 34 |
| C033 Phase 33 removed from main | C034 Phase 34 | C035 Phase 35 |
| C034 Phase 34 removed from main | C035 Phase 35 | C036 Phase 36 |
| C035 Phase 35 removed from main | C036 Phase 36 | C037 Phase 37 |
| C036 Phase 36 removed from main | C037 Phase 37 | C038 Phase 38 |
| C037 Phase 37 removed from main | C038 Phase 38 | C039 Phase 39 |
| C038 Phase 38 removed from main | C039 Phase 39 | C040 Phase 40 |
| C039 Phase 39 removed from main | C040 Phase 40 | C041 Phase 41 |
| C040 Phase 40 removed from main | C041 Phase 41 | C042 Phase 42 |
| C041 Phase 41 removed from main | C042 Phase 42 | C043 Phase 43 |
| C042 Phase 42 removed from main | C043 Phase 43 | C044 Phase 44 |
| C043 Phase 43 removed from main | C044 Phase 44 | C045 Phase 45 |
| C044 Phase 44 removed from main | C045 Phase 45 | C046 Phase 46 |
| C045 Phase 45 removed from main | C046 Phase 46 | C047 Phase 47 |
| C046 Phase 46 removed from main | C047 Phase 47 | C048 Phase 48 |
| C047 Phase 47 removed from main | C048 Phase 48 | C049 Phase 49 |
| C048 Phase 48 removed from main | C049 Phase 49 | C050 Phase 50 |
| C049 Phase 49 removed from main | C050 Phase 50 | C051 Phase 51 |
| C050 Phase 50 removed from main | C051 Phase 51 | C052 Phase 52 |
| C051 Phase 51 removed from main | C052 Phase 52 | C053 Phase 53 |
| C052 Phase 52 removed from main | C053 Phase 53 | C054 Phase 54 |
| C053 Phase 53 removed from main | C054 Phase 54 | C055 Phase 55 |
| C054 Phase 54 removed from main | C055 Phase 55 | C056 Phase 56 |
| C055 Phase 55 removed from main | C056 Phase 56 | C057 Phase 57 |
| C056 Phase 56 removed from main | C057 Phase 57 | C058 Phase 58 |
| C057 Phase 57 removed from main | C058 Phase 58 | C059 Phase 59 |
| C058 Phase 58 removed from main | C059 Phase 59 | C060 Phase 60 |
| C059 Phase 59 removed from main | C060 Phase 60 | C061 Phase 61 |
| C060 Phase 60 removed from main | C061 Phase 61 | C062 Phase 62 |
| C061 Phase 61 removed from main | C062 Phase 62 | C063 Phase 63 |
| C062 Phase 62 removed from main | C063 Phase 63 | C064 Phase 64 |
| C063 Phase 63 removed from main | C064 Phase 64 | C065 Phase 65 |
| C064 Phase 64 removed from main | C065 Phase 65 | C066 Phase 66 |
| C065 Phase 65 removed from main | C066 Phase 66 | C067 Phase 67 |
| C066 Phase 66 removed from main | C067 Phase 67 | C068 Phase 68 |
| C067 Phase 67 removed from main | C068 Phase 68 | C069 Phase 69 |
| C068 Phase 68 removed from main | C069 Phase 69 | C070 Phase 70 |
| C069 Phase 69 removed from main | C070 Phase 70 | C071 Phase 71 |
| C070 Phase 70 removed from main | C071 Phase 71 | C072 Phase 72 |
| C071 Phase 71 removed from main | C072 Phase 72 | C073 Phase 73 |
| C072 Phase 72 removed from main | C073 Phase 73 | C074 Phase 74 |
| C073 Phase 73 removed from main | C074 Phase 74 | C075 Phase 75 |
| C074 Phase 74 removed from main | C075 Phase 75 | C076 Phase 76 |
| C075 Phase 75 removed from main | C076 Phase 76 | C077 Phase 77 |
| C076 Phase 76 removed from main | C077 Phase 77 | C078 Phase 78 |
| C077 Phase 77 removed from main | C078 Phase 78 | C079 Phase 79 |
| C078 Phase 78 removed from main | C079 Phase 79 | C080 Phase 80 |
| C079 Phase 79 removed from main | C080 Phase 80 | C081 Phase 81 |
| C080 Phase 80 removed from main | C081 Phase 81 | C082 Phase 82 |
| C081 Phase 81 removed from main | C082 Phase 82 | C083 Phase 83 |
| C082 Phase 82 removed from main | C083 Phase 83 | C084 Phase 84 |
| C083 Phase 83 removed from main | C084 Phase 84 | C085 Phase 85 |
| C084 Phase 84 removed from main | C085 Phase 85 | C086 Phase 86 |
| C085 Phase 85 removed from main | C086 Phase 86 | C087 Phase 87 |
| C086 Phase 86 removed from main | C087 Phase 87 | C088 Phase 88 |
| C087 Phase 87 removed from main | C088 Phase 88 | C089 Phase 89 |
| C088 Phase 88 removed from main | C089 Phase 89 | C090 Phase 90 |
| C089 Phase 89 removed from main | C090 Phase 90 | C091 Phase 91 |
| C090 Phase 90 removed from main | C091 Phase 91 | C092 Phase 92 |
| C091 Phase 91 removed from main | C092 Phase 92 | C093 Phase 93 |
| C092 Phase 92 removed from main | C093 Phase 93 | C094 Phase 94 |
| C093 Phase 93 removed from main | C094 Phase 94 | C095 Phase 95 |
| C094 Phase 94 removed from main | C095 Phase 95 | C096 Phase 96 |
| C095 Phase 95 removed from main | C096 Phase 96 | C097 Phase 97 |
| C096 Phase 96 removed from main | C097 Phase 97 | C098 Phase 98 |
| C097 Phase 97 removed from main | C098 Phase 98 | C099 Phase 99 |
| C098 Phase 98 removed from main | C099 Phase 99 | C100 Phase 100 |

Has Brainstorming 5 Whys Fishbone diagrams been used to identify possible root causes? Has the data been analyzed graphically to investigate the clues within?

Faults are manifested as errors, which in turn are manifested as failures (Avizienis, 2004). A failure pattern describes how a failure is produced from a fault, identifies the components which are involved in the failure, the specific errors which allowed the failure to occur, and the effect of the failure on the system. If the failure was intentional (instead of produced by an accidental fault), it can also be described. The failure pattern also provides a solution to avoid this failure in the form of reliability and security patterns, as well as a way to store and analyze the information collected at each stage of the failure. Due to their dynamic descriptions, failure patterns allow countermeasures to be included to mitigate the identified failures.

The secondary equipment on 2300C are exhibiting failures in the patterns of B and C Wear Out and Fatigue respectively. Mainly because of inadequate or no proactive maintenance procedures.

If an FMEA was completed, what risks were identified for reduction? What if any hypothesis tests were used? Why? In what ways was the data collected stratified?



Have hypothesis tests been used where applicable to verify observations made from the graphical analysis? Has the data been stratified where possible for clues?

Pattern A This is the most famous failure pattern. It's commonly known as bathtub, due to its shape. We can identify three main zones. First, a high failure probability at the beginning of the operating life that decreases until it became stable. This zone is called infant mortality and means that when we install a new component there is an initial high risk of failure. The second zone is the rest of the useful life with a lower and constant failure probability. Finally, at the end, we identify a wear-out zone. In this pattern, replacing the component before reaching this last zone will reduce the failure probability. However, we need to take into consideration that we are also introducing high chances of early failures due to infant mortality.

Pattern C In this pattern, the conditional probability increases at a constant rate along the life of the component. We can't identify a definite wear-out zone so, there isn't an optimum time to replace the item. Nevertheless, we could replace the component when the failure probability reaches a certain value

What are the key ways in which the process or product fails in the mode or how it manifests itself? What if any hypothesis tests were used initially and Why?

Pattern B. This pattern is the same as the previous one but without the infant mortality zone at the beginning. Sometimes the absence of this initial zone is a characteristic of the component itself and other times is because the manufacturer had eliminated all the components with early defects. This elimination process is commonly known as burnout test.As well as in the pattern A, replacing the component before the wear-out zone is a good way of reducing the chances of failure and in this particular case we are not introducing extra failure possibilities due to infant mortality.

Pattern D This pattern shows a really low probability of failure at the beginning of the component's life which then increases up to a certain level that remain constant through the rest of its operating life. It's worth remarking that this area with a constant conditional probability shows us that the failures occur randomly. In this way, the replacement of a component won't bring up any benefit except for the already mentioned brief period of low failure probability at the beginning, which is truly insignificant compared to the rest of the useful life of the

Has correlation and regression techniques been used if applicable to understand and quantify the relationships between the critical process inputs and outputs?

Pattern E This pattern shows a constant failure probability along the component's life. We call this pattern a random failure distribution. Here, there is nothing that a component replacement can do to reduce the probability of a failure.

Pattern F This pattern is also a random failure distribution, but with an infant mortality area at the beginning. In this case, replacing a component

SIX SIGMA PROJECT CHARTER - IMPROVE - SECONDARY EQUIPMENT

P6

| | | | | Week № | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | | | | | | | | | | | | |
|--------------|--|----------------------------|---|--------|-------|--------|--------|--------|--------|-------|--------|--------|--------|-------|--------|--------|--------|-------|--------|--------|--------|-------|-------|--------|--------|--------|-------|--------|--------|--------|-------|--------|--------|--------|-------|-------|--------|--------|--------|-------|--------|--------|--------|-------|--------|--------|--------|--------|-------|--------|--------|--------|-------|--------|--------|--------|--|--|--|--|--|--|--|--|--|--|--|--|
| No | Action Item | Responsible | Due Date | Status | 3-Jan | 10-Jan | 17-Jan | 24-Jan | 31-Jan | 7-Feb | 14-Feb | 21-Feb | 28-Feb | 7-Mar | 14-Mar | 21-Mar | 28-Mar | 4-Apr | 11-Apr | 18-Apr | 25-Apr | 2-May | 9-May | 16-May | 23-May | 30-May | 6-Jun | 13-Jun | 20-Jun | 27-Jun | 4-Jul | 11-Jul | 18-Jul | 25-Jul | 1-Aug | 8-Aug | 15-Aug | 22-Aug | 29-Aug | 5-Sep | 12-Sep | 19-Sep | 26-Sep | 3-Oct | 10-Oct | 17-Oct | 24-Oct | 31-Oct | 7-Nov | 14-Nov | 21-Nov | 28-Nov | 5-Dec | 12-Dec | 19-Dec | 26-Dec | | | | | | | | | | | | |
| 11.08 | Mark out on floor all work in process, finished goods, work stands, racks, carts, purchased components and equipment using color coded floor tape per standard color coding scheme | F. Webberking | 20-May-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 11.09 | Mark out on floor fleece container and scrap container location using 2" yellow and red floor tape respectively on 2300A and 2300B. | F. Webberking | 14-May-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 12.00 | 0010-3011036 - 2300C IMM PRODUCTION LINE CELL | | PERMANENTLY MOUNT A TALKIE TALKIE TO I BEAM B19 NEXT TO 2300C - This is to improve the response time and communication when operations needs help. Walkie talkie keeps going missing and operator wastes time either looking for | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 12.01 | Obtain walkie talkie | F. Webberking | 04-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 12.01 | Make mounting plate | F. Webberking | 11-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 12.01 | Glue using JB Weld all components of the walkie talkie to the walkie talkie | F. Webberking | 25-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 12.01 | Mount plate and walkie talkie to I beam B19 next to 2300C | F. Webberking | 26-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 12.01 | Make notice sign and affix to I beam B19 | F. Webberking | 27-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 13.00 | 0010-3011036 - 2300C IMM PRODUCTION LINE CELL | | IMM 2300C PRODUCTION LINE # 3011036 SECONDARY EQUIPMENT - Add the all the discrete secondary equipment in JOT Form so technicians can select each machine that they have worked on | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 13.01 | Conduct awareness training to all maintenance and automation technicians on 1st, 2nd and 3rd shifts of the results of 2300C survey and of impending focused improvement project. | F. Webberking | 23-Sep-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 13.02 | Add all secondary equipment as a sub group to 2300C Injection Molding Machine in JOT using physical asset numbers and description as it appears in SAP 3017221 ASSEMBLY 1 (0060) 3017231 ASSEMBLY 2 (0070) 3017213 HELIUM LEAK TESTER CHAMBER 1 (0050) 3017213 HELIUM LEAK TESTER CHAMBER 2 (0050) 3017192 PUMP HOT PLATE WELDER (0030) 3017193 SHELL TO SHELL WELDER (0040) 3017194 UPPER SHELL ASSEMBLY (0020) 3017195 END OF LINE TESTER (0080) | S. Pardeller | 11-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 13.03 | Inform all affected employees (maintenance, automation process technicians and engineers) of secondary equipment additions made to JOT under 2300C and to fill out work reports accordingly. | S. Pardeller | 15-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 13.04 | Provide Fred Webberking (CI Engineer) with all Original Equipment Manufacturers of 2300C secondary equipment contact information. Names, addresses, emails, web addresses, contact phone numbers etc. | S. Pardeller | 04-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 13.05 | Provide Fred Webberking (CI Engineer) with copies of new BR167 vent hose installation tooling modifications paperwork, technical drawings, plans and any in-house tooling, fixtures and fittings available to date. (Keaton Walker) When will new fixture be installed? | K. Walker | 31-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 13.06 | Train affected maintenance and automation technicians in P-M Analysis advanced problem solving methodology. | F. Webberking | 31-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 14.00 | 0010-3011036 - 2300C IMM PRODUCTION LINE CELL | | CONDUCT A FAILURE ANALYSIS REPORT CORRECTIVE ACTION SYSTEM SURVEY OF ALL SECONDARY EQUIPMENT - Baseline current equipment performance with regards to uptime availability | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 14.01 | Base line defects and rejection reasons for all SCR tank part types from 0030-3017194 Shell To Shell Welder and the same for all SCR part types from 0080-3017195 End Of Line Tester and the same for all SCR part types from 0050-3017213 Helium Leak Tester. | F. Webberking K. Walker | 15-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SIX SIGMA PROJECT CHARTER - IMPROVE - SECONDARY EQUIPMENT

P6

| № | Action Item | Responsible | Due Date | Status | Week № | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-------|--|--|------------|--------|--------|---|---|---|---|---|---|---|---|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|--|
| | | | | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | |
| 14.02 | Export raw data part reject history information from 0040-3017193 Shell To Shell Welder data acquisition register. Convert and stratify collected information into part types, occurrences and durations. | F. Webberking | 15-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 14.03 | Export raw data part reject history information from 0080-3017195 End Of Line Tester data acquisition register. Convert and stratify collected information into part types, occurrences and durations. | F. Webberking. | 15-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 14.04 | Export raw data part reject history information from 0050-3017213 Helium Leak Tester data acquisition register. Convert and stratify collected information into part types, occurrences and durations. | K. Walker | 15-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 14.05 | Export JOT maintenance report records from 05/11/21 - 10/08/21 for 0030-3017193 Shell To Shell Welder. Stratify information by machine - type of equipment - type of activity - work category - problem description to sort and filter for patterns of failure and breakdown types to occurrences and durations. | F. Webberking | 15-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 14.06 | Export JOT maintenance report records from 05/11/21 - 10/08/21 for 0080-3017195 End Of Line Tester. Stratify information by machine - type of equipment - type of activity - work category - problem description to sort and filter for patterns of failure and breakdown types to occurrences and durations. | K. Walker | 15-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 14.07 | Export weekly JOT maintenance report records. Stratify information by machine - type of equipment - type of activity - work category - problem description to sort and filter for patterns of failure and breakdown types to occurrences and durations. Plan corrective actions accordingly. Based on analysis. | F. Webberking K. Walker | 25-Oct-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.00 | 0010-3011036 - 2300C IMM PRODUCTION LINE CELL | REPLACE ALL WORN, MISSING, BROKEN OR REMOVED PARTS AND COMPONENTS FROM ALL SECONDARY EQUIPMENT MACHINES AND SECONDARY EQUIPMENT FIXTURES - Strategic dedicated spares parts | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.01 | Leifers TEC Conduct a survey to establish which of all the machines and of all fixtures and tooling for each product type that runs on the line has worn, missing, broken or removed parts, tools and components. | F. Webberking | 11/31/2021 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.02 | Document all parts that need to be either re-ordered as replacements or upgraded and send RFQ to vendor | F. Webberking | 06-Dec-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.03 | Receive quote from original equipment manufacturers Leifers and HeTech. | F. Webberking | 31-Dec-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.04 | Enter BANF into SAP for replacement parts from original equipment manufactures. | F. Webberking | 31-Dec-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.05 | BANF routing approval lead time to PO release issue | F. Webberking | 10-Jan-22 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.06 | Vendor lead time | F. Webberking | 04-Mar-22 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.07 | Receive replacement spare parts from vendor | F. Webberking | 04-Mar-22 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.08 | Install all replacement parts to all fixtures to all secondary equipment | F. Webberking | 30-Apr-22 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.09 | Install all received replacement parts to all secondary machines | F. Webberking | 30-Apr-22 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.10 | Register all remaining replacement parts as spare parts into our spare parts store room | F. Webberking | 30-Apr-22 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 15.08 | HeTech Marposs Conduct a survey to establish which of all the machines and of all fixtures and tooling for each product type that runs on the line has worn, missing, broken or removed parts, tools and components. | F. Webberking | 31-Dec-21 | ● | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SIX SIGMA PROJECT CHARTER - COUNTERMEASURES - SECONDARY EQUIPMENT

| Item No | Action Item No | Associated Action Item | Problem | Countermeasure | Responsible | Original Date | New Due Date | Status |
|---------|----------------|--|---|--|---------------|---------------|--------------|---------------------------------------|
| 1.00 | 12.01 | Add all secondary equipment as a sub group to 2300C Injection Molding Machine in JOT using physical asset numbers and description as it appears in SAP 3017221 ASSEMBLY 1 (0060) 3017231 ASSEMBLY 2 (0070) 3017213 HELUIM LEAK TESTER CHAMBER 1 (0050) 3017213 HELUIM LEAK TESTER CHAMBER 2 (0050) 3017192 PUMP HOT PLATE WELDER (0030) 3017193 SHELL TO SHELL WELDER (0040) 3017194 UPPER SHELL ASSEMBLY (0030) | Awaiting information regarding cost centers from accounting specifically to come from Harrison Musselman or Benedict Schneider. Information required to complete associated action item. | Request information from Harrison Musselman or Benedict Schneider to be forwarded to Stefan Pardeller no later than 10/19/21. | S. Pardeller | 15-Oct-21 | 01-Nov-21 | ● |
| 2.00 | 12.02 | Inform all affected employees (maintenance, automation process technicians and engineers) of secondary equipment additions made to JOT under 2300C and to fill out work reports accordingly. | This action item is a successor to Action Item 12.01 | Complete predecessor Action Item 12.01 | S. Pardeller | 16-Oct-21 | 01-Nov-21 | ● |
| 3.00 | 19.05 | MODIFY THE FLARING TOOL ON 0020-3017194 - This has been a long standing problem. of the vent pipe not being flared to allow to come into alignment the SCR tank barb fitting during installaton. The idea here is to make and install a conical flaring tool to flare the end of pipe. | I finished the prototype part and installed it and ran a 30 piece study to check for performance and it is working very good and the flare a the end of the vent pipe helps align the end of the vent pipe with the barb better and it doesn't 'crash' by misalignment. | I would like to now make a permanent tool make in one piece from A2 steel and case hardened. I will have Diversity Machine make the new flaring tool. I will then submit the drawing to the maintenance or automation department. | F. Webberking | 08-Nov-21 | 30-Dec-21 | ● |
| 4.00 | 15.00 | REPLACE ALL WORN, MISSING, BROKEN OR REMOVED PARTS AND COMPONENTS FROM ALL SECONDARY EQUIPMENT MACHINES AND SECONDARY EQUIPMENT FIXTURES - Strategic dedicated spare | All of the tooling parts do not fit either tooling to fixture or tooling to tooling or tooling to parts. In many cases it simply looks like it's the wrong version | I will take plan a time during the week of 03/28/22 to remove all the tooling for fixtures for MBUSI BR67 and for all BMW and take the parts to local machine shop to have them all measured and compared to the new replacement tooling to see what can be modified and what has to be completely remade and have the machine provide me with a quote for this work | F. Webberking | 25-Mar-22 | 15-Apr-22 | ● |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| | | | | | | | |
|--|--|--|--|--|--|--|--|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

SIX SIGMA PROJECT CHARTER - CONTROL

PROJECT TITLE 2300C PRODUCTION LINE SCRAP REDUCTION & SECONDARY EQUIPMENT RELIABILITY IMPROVEMENT

Have ongoing KPIs been developed to monitor performance? Has the project report been completed, and lessons learnt communicated to other relevant areas?

What next? Is there anywhere else in the organization that the lessons learnt from this project can be used? By how much did the problem and COPQ reduce by?

Have they been integrated into the organizations' KPIs structure (dashboards, storyboards, MDI boards, scorecards etc.) where possible and or necessary?

How were the ongoing KPIs selected? Have the temporary data collection plans for the project been removed? Who owns the KPIs now? Who will be monitoring them?

Have data collection plans for the ongoing KPIs been implemented as 'business as usual'? Do the KPIs and data collection plans have clear owners?

What has been done to ensure the improvements have become business as usual and won't 'fall over' after the project closes? What are the validated project savings?

Have relevant graphical and statistical techniques been implemented to help the new owners monitor and review process performance? (SPC, histograms, run charts)

Have the new KPI owners been helped to understand how to monitor the KPIs? How will we know if the process performance deteriorates? What alarm bells will ring?

Have the improvements been documented, 'standardized' and become 'business as usual'? Where did the savings eventually come from? (efficiency, cash, benefits?)

Have the improvements in the KPIs been quantified, and new baselines established? Have the project savings been calculated and signed off with finance department?

SIX SIGMA PROJECT CHARTER - CONTROL PLAN


P13

| | | | | | | | |
|--|---|----------------------|--|----------------|-----------------|-------------------|-----------|
| PRODUCT / PART / MATERIAL / COMPONENT NAME | SCR Tank | CUSTOMER ME APPROVAL | | PREPARATION BY | Fred Webberking | PLAN DATE (ORG.) | 01-Jan-20 |
| PRODUCT / PART / MATERIAL / COMPONENT DESCRIPTON | SCR Tank BR167 MBUSI | CUSTOMER QA APPROVAL | | PROCESS OWNER | | PLAN RELEASE DATE | 02-Jan-20 |
| PRODUCT / PART / MATERIAL / COMPONENT NUMBER | SAP MAT. # 112513903 / P/N: A1674708202 | CUSTOMER PE APPROVAL | | | | PLAN DATE (REV.) | 03-Jan-20 |

THE CONTROL PLAN DOCUMENTS THE ELEMENTS OF A QUALITY ASSURANCE SYSTEM THAT ARE TO BE IMPLEMENTED IN ORDER TO ASSURE THAT QUALITY STANDARDS ARE MET FOR A PARTICULAR PRODUCT. THE CONTROL PLAN FORMALIZES THE SYSTEM OF CONTROLS THAT WILL BE UTILIZED





| PROCES | | CRITICAL TO QUALITY (Y) - (X) | | MACHINE DEVICE TOOL JIG | CHARACTERISTICS | | | GAUGE | METHODS | | | | | RESPONSIBLE | MISTAKE PROOFING | WORK INSTRUCTIONS | REACTION PLAN | |
|--------|----------------------------|-------------------------------|------|-------------------------|-----------------|------------|---------|-------|------------------|-------|----------------------------------|----------|------------|------------------------|------------------------|--------------------|--------------------------------|--------------------------|
| № | PROCESS / WORK DESCRIPTION | KPIV | KPOV | | № | PRODUCT | PROCESS | | TOLERANCE | | EVALUATION MEASUREMENT TECHNIQUE | SAMPLING | | | | | | CONTROL METHOD |
| | | | | UCL | | | | LCL | SIZE | FREQ. | | | | | | | | |
| 1.00 | Plastic Injection Molding | X | | 2300C 6705 Tool | 1.00 | Appearance | Visual | N/A | No Scratch Marks | | Visual Inspection | 100% | Every Part | 100% Visual Inspection | Shift Machine Operator | Operator Dependent | See Standard Work Instructions | Notify Quality Assurance |
| 1.01 | | | | | 1.01 | | | | | | | | | | | | | |
| 1.02 | | | | | 1.02 | | | | | | | | | | | | | |
| 1.03 | | | | | 1.03 | | | | | | | | | | | | | |
| 1.04 | | | | | 1.04 | | | | | | | | | | | | | |
| 1.05 | | | | | 1.05 | | | | | | | | | | | | | |
| 1.06 | | | | | 1.06 | | | | | | | | | | | | | |
| 1.07 | | | | | 1.07 | | | | | | | | | | | | | |
| 1.08 | | | | | 1.08 | | | | | | | | | | | | | |
| 1.09 | | | | | 1.09 | | | | | | | | | | | | | |
| 1.10 | | | | | 1.10 | | | | | | | | | | | | | |
| 1.11 | | | | | 1.11 | | | | | | | | | | | | | |
| 1.12 | | | | | 1.12 | | | | | | | | | | | | | |
| 2.00 | | | | | 2.00 | | | | | | | | | | | | | |
| 2.01 | | | | | 2.01 | | | | | | | | | | | | | |
| 2.02 | | | | | 2.02 | | | | | | | | | | | | | |
| 2.03 | | | | | 2.03 | | | | | | | | | | | | | |
| 2.04 | | | | | 2.04 | | | | | | | | | | | | | |
| 2.05 | | | | | 2.05 | | | | | | | | | | | | | |
| 2.06 | | | | | 2.06 | | | | | | | | | | | | | |
| 2.07 | | | | | 2.07 | | | | | | | | | | | | | |
| 2.08 | | | | | 2.08 | | | | | | | | | | | | | |
| 2.09 | | | | | 2.09 | | | | | | | | | | | | | |
| 2.10 | | | | | 2.10 | | | | | | | | | | | | | |
| 2.12 | | | | | 2.12 | | | | | | | | | | | | | |
| 3.00 | | | | | 3.00 | | | | | | | | | | | | | |
| 3.01 | | | | | 3.01 | | | | | | | | | | | | | |
| 3.02 | | | | | 3.02 | | | | | | | | | | | | | |
| 3.03 | | | | | 3.03 | | | | | | | | | | | | | |
| 3.04 | | | | | 3.04 | | | | | | | | | | | | | |
| 4.05 | | | | | 4.05 | | | | | | | | | | | | | |
| 3.06 | | | | | 3.06 | | | | | | | | | | | | | |
| 3.07 | | | | | 3.07 | | | | | | | | | | | | | |
| 3.08 | | | | | 3.08 | | | | | | | | | | | | | |
| 3.09 | | | | | 3.09 | | | | | | | | | | | | | |
| 3.10 | | | | | 3.10 | | | | | | | | | | | | | |
| 3.11 | | | | | 3.11 | | | | | | | | | | | | | |
| 3.12 | | | | | 3.12 | | | | | | | | | | | | | |

1.00 CONDUCT A FARCAS (FAILURE ANALYSIS REPORT CORRECTIVE ACTION SYSTEM) - This is to assess critical dedicated spare parts usage on 2300C to recognize any patterns of high usage.

| | | | |
|---|--|--|--|
| <p>SCREEN PICTURE OF SPARE PARTS WAREHOUSE CLERK</p>  <p>PICTURE 1.01</p> | <p>TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE</p> <p>INSERT PICTURE HERE</p> <p>PICTURE 1.02</p> | <p>TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE</p> <p>INSERT PICTURE HERE</p> <p>PICTURE 1.30</p> | <p>TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE</p> <p>INSERT PICTURE HERE</p> <p>PICTURE 1.04</p> |
|---|--|--|--|

PHOTOGRAPHIC EVIDENCE - INJECTION MOLDING MACHINE

4.00 INSTALL A MANUALLY CONTROLLED PNEUMATICALLY OPERATED THROAT SLIDE VALVE ON - This is to alleviate the need to manually operate the slide valve by hand





| | | | |
|---|---|---|---|
| <p>PROPOSAL FROM ENGEL FUTURE STATE AIR CONTROLLED</p>  <p>Pneumatic material hopper isolation</p> <ol style="list-style-type: none"> [1] Material hopper displacement unit [2] shut-off solenoid [3] Pneumatic valve [4] Connection for air maintenance unit [5] Pneumatic cylinder [6] non-contact end position switch <p>PICTURE 4.01</p> | <p>CURRENT STATE MANUALLY OPERATED SLIDE VALVE</p>  <p>PICTURE 4.02</p> | <p>MY OWN DESIGN (VALVE OPEN)</p>  <p>PICTURE 4.03</p> | <p>MY OWN DESIGN (VALVE CLOSED)</p>  <p>PICTURE 4.04</p> |
|---|---|---|---|

PHOTOGRAPHIC EVIDENCE - SECONDARY EQUIPMENT





22.00 EXTEND ALIGNMENT 'FORKS' ON VS30 NUMBER 3 BUSHING FIXTURE FOR EOLT 3017195-0080 - Currently there is very little alignment of the bushing to the mounting leg hole before bushing is pressed in

| | | | |
|---|---|--|--|
| <p>VS30 ALIGNMENT 'FORKS' - AFTER</p>  <p>PICTURE 16.01</p> | <p>TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE</p>  <p>PICTURE 16.02</p> | <p>TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE</p>  <p>PICTURE 16.03</p> | <p>TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE</p>  <p>PICTURE 16.04</p> |
|---|---|--|--|





PHOTOGRAPHIC EVIDENCE - SECONDARY EQUIPMENT

| | | | | |
|--|---|--|--|--|
| 16.00 EXTEND ALIGNMENT 'FORKS' ON VS30 NUMBER 3 BUSHING FIXTURE FOR EOLT 3017195-0080 - Currently there is very little alignment of the bushing to the mounting leg hole before bushing is pressed in | | | | |
| VS30 ALIGNMENT PEINE GERMANY  | TITLE OR DESCRIPTON OF PHOTOGRAPHIC EVIDENCE HERE  | TITLE OR DESCRIPTON OF PHOTOGRAPHIC EVIDENCE HERE  | TITLE OR DESCRIPTON OF PHOTOGRAPHIC EVIDENCE HERE  | |
| PICTURE 16.05 | PICTURE 16.06 | PICTURE 16.07 | PICTURE 16.08 | |





PHOTOGRAPHIC EVIDENCE - SECONDARY EQUIPMENT

| | | | | |
|---|---|--|--|--|
| 19.00 MODIFY THE FLARING TOOL ON 0020-3017194 - This has been a long standing problem. of the vent pipe not being flared to allow to come into alignment the SCR tank barb fitting during installaton. The idea here is to make and install a conical flaring tool to flare the end of pipe. | | | | |
| FLARING TOOL OLD - BEFORE  | FLARING TOOL NEW - AFTER  | FLARING TOOL NEW - AFTER VERSION 2  | FLARING TOOL NEW - FINAL VERSION 3  | |
| PICTURE 19.01 | PICTURE 19.02 | PICTURE 19.03 | PICTURE 19.04 | |


PHOTOGRAPHIC EVIDENCE - SECONDARY EQUIPMENT

| | | | | |
|---|--|---|---|--|
| 20.00 REPLACE WORN OUT ASSEMBY 2 VENT PIPE GRIPPER TOOL - Currently we are gluing sand paper to the gripper tools because there is insufficient friction force between the inner contact surface of the vent hose gripper tools and the outside surface wall of the vent | | | | |
| FRONT  | BACK  | SIDE A  | SIDE B  | |
| PICTURE 20.10 | PICTURE 20.02 | PICTURE 20.03 | PICTURE 20.04 | |



PHOTOGRAPHIC EVIDENCE - SECONDARY EQUIPMENT

| | | | | | | | | | | | | | | | | |
|--|---------------|-------------------|---------------|----|---|----------|-------------------|---|---|--|--------|--|---|---|---|--|
| 20.00 REPLACE WORN OUT ASSEMBY 2 VENT PIPE GRIPPER TOOL - Currently we are gluing sand paper to the gripper tools because there is insufficient friction force between the inner contact surface of the vent hose gripper tools and the outside surface wall of the vent | | | | | | | | | | | | | | | | |
| DRAWING OF VENT PIPE GRIPPER TOOL  <small>ALL DIMENSIONS ARE IN MILLIMETERS MATERIAL: A2 STEEL MITRE (CASE HARDENING)</small> <small>2300C BMW G05/G06/G07 ASSEMBLY 2 VENT PIPE GRIPPER TOOL</small> <small>Notes: As mentioned on the drawing I need to have the inside wall of the gripper treated with a "sand paper" application process called Electro Spark Carbonize Deposition to the grade of #3, 00F or 300grit equivalent. Please let me know if you are able to do this.</small> <small>DRAWN BY: FRED WEBBERING ENGINEER: FRED WEBBERING AUTOMOTIVE CONTACT: 864-257-2330 fwebbering@cashtrig.com</small> <table border="1"> <tr> <td>REV</td> <td>DATE</td> <td>DESC</td> <td>BY</td> </tr> <tr> <td>1</td> <td>11/09/21</td> <td>Q-D08-G05-G06-G07</td> <td>A</td> </tr> <tr> <td>2</td> <td></td> <td>MR. C3</td> <td></td> </tr> </table> | REV | DATE | DESC | BY | 1 | 11/09/21 | Q-D08-G05-G06-G07 | A | 2 | | MR. C3 | | PDF OF VENT PIPE GRIPPER TOOL  2300C BMW G05.G06.G07 Assembly 2 Vent | 3D DRAWING OF GRIPPER  DA676102.step | NEW REPLACEMENT GRIPPER BEFORE CASE HARDENING  | |
| REV | DATE | DESC | BY | | | | | | | | | | | | | |
| 1 | 11/09/21 | Q-D08-G05-G06-G07 | A | | | | | | | | | | | | | |
| 2 | | MR. C3 | | | | | | | | | | | | | | |
| PICTURE 20.05 | PICTURE 20.06 | PICTURE 20.07 | PICTURE 20.08 | | | | | | | | | | | | | |


PHOTOGRAPHIC EVIDENCE - SECONDARY EQUIPMENT

| | | | | |
|---|---|---|---|--|
| 20.00 REPLACE WORN OUT ASSEMBY 2 VENT PIPE GRIPPER TOOL - Currently we are gluing sand paper to the gripper tools because there is insufficient friction force between the inner contact surface of the vent hose gripper tools and the outside surface wall of the vent | | | | |
| ILLUSTRATION OF MODIFIED GRIPPER TOOL  | TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE | TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE | TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE | |
| PICTURE 20.09 | PICTURE 20.10 | PICTURE 20.11 | PICTURE 20.12 | |


PHOTOGRAPHIC EVIDENCE

| | | | | |
|--|---|---|---|--|
| 21.00 LINE STOP AUTHORITY SINGLE CYCLING THE INJECTION MOLDING MACHINE - Institutionalize line stop authority by training authorized personnel to single cycle the injection molding machine when any one of the second equipment broken down to contain 'missing | | | | |
| ONE POINT LESSON SINGLE CYCLE 2300C  Single Point Lesson - Single Cycling 2300C Injection | TRAINING SIGN IN SHEET  Xerox Scan_01212022 105320.pdf | TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE <p style="text-align: center; color: red;">INSERT PICTURE HERE</p> | TITLE OR DESCRIPTION OF PHOTOGRAPHIC EVIDENCE HERE <p style="text-align: center; color: red;">INSERT PICTURE HERE</p> | |
| PICTURE 21.01 | PICTURE 21.02 | PICTURE 21.03 | PICTURE 21.04 | |





PHOTOGRAPHIC EVIDENCE

| | | | | |
|---|---|---|---|---|
| 22.00 REPLACE SILICONE RUBBER BUSHINGS ON 0080-3017195 END OF LINE TESTER FOR BR167 FIXTURE - One of the bushings was missing and three others were worn out | | | | |
| TITLE OR DEScriptON OF PHOTOGRAPHIC EVIDENCE HERE | TITLE OR DEScriptON OF PHOTOGRAPHIC EVIDENCE HERE | TITLE OR DEScriptON OF PHOTOGRAPHIC EVIDENCE HERE | TITLE OR DEScriptON OF PHOTOGRAPHIC EVIDENCE HERE | TITLE OR DEScriptON OF PHOTOGRAPHIC EVIDENCE HERE |
|  | INSERT PICTURE HERE | INSERT PICTURE HERE | INSERT PICTURE HERE | INSERT PICTURE HERE |
| PICTURE 22.01 | PICTURE 22.02 | PICTURE 22.03 | PICTURE 22.04 | |

PHOTOGRAPHIC EVIDENCE

| | | | | |
|---|---|---|---|---|
| 23.00 0040-3017193 SHELL TO SHELL HOT PLATE WELDER DOOR SAFETY RELAY - The latest equipment abnormal phenomenon is with the 0040-3017193 Shell To Shell Hot Plate Welder. Occasionally we will have a machine stoppage and error which will display on the control panel screen 'Welding mac | | | | |
| ALBANY DOOR CLOSE PROBLEM SOLUTION | TITLE OR DEScriptON OF PHOTOGRAPHIC EVIDENCE HERE | TITLE OR DEScriptON OF PHOTOGRAPHIC EVIDENCE HERE | TITLE OR DEScriptON OF PHOTOGRAPHIC EVIDENCE HERE | TITLE OR DEScriptON OF PHOTOGRAPHIC EVIDENCE HERE |
|  Albany Door closed problem solution.pdf | INSERT PICTURE HERE | INSERT PICTURE HERE | INSERT PICTURE HERE | INSERT PICTURE HERE |
| PICTURE 23.01 | PICTURE 23.02 | PICTURE 23.03 | PICTURE 23.04 | |


PHOTOGRAPHIC EVIDENCE

| | | | | |
|--|--|---|---|--|
| 24.00 0040-3017192 REFURBISH PUMP TO SHELL WELDER WORN TOOLING FOR VS30 - The latest equipment abnormal phenomenon is with the 0040-3017193 Shell To Shell Hot Plate Welder. Occasionally we will have a machine stoppage and error which will display on | | | | |
| VS30 MEMBRANE CHECK VALVE WELD FIXTURE | MENBRANE CHECK VALVE | SCREEN SHOT 1 | SCREEN SHOT 2 | |
|  |  |  |  | |
| PICTURE 24.01 | PICTURE 24.02 | PICTURE 24.03 | PICTURE 24.04 | |

PHOTOGRAPHIC EVIDENCE


25.00 0040-3017192 PUMP TO SHELL WELDER - The latest equipment abnormal phenomenon is with the 0040-3017193 Shell To Shell Hot Plate Welder. Occasionally we will have a machine stoppage and error which will display on

ILLUSTRATION 1




PICTURE 25.01

ILLUSTRATION 2




PICTURE 25.02

ILLUSTRATION 3



PICTURE 25.03


ILLUSTRATION 4




PICTURE 25.04

PHOTOGRAPHIC EVIDENCE


25.00 REPLACE MRO OR TYPE SUCTION CUPS BEING SUBSTITUTED FOR ALL PART TYPES FIXTURES - I have found that many of the suction cups used in the fixtures for the different part types used in this machine have been replaced with incorrect non-standard non-original suction cups with a mixture




PICTURE 25.01



PICTURE 25.02



PICTURE 25.03




PICTURE 25.04

PHOTOGRAPHIC EVIDENCE


25.00 THERMO IMAGES - thermo images of BR167

UPPER SHELL PART TEMPERATURES AT END OF EXIT CONVEYOR



PICTURE 25.01

UPPER SHELL PART TEMPERATURES AT SHELL TO SHELL WELDER



PICTURE 25.02

INSERT PICTURE HERE


PICTURE 25.03

INSERT PICTURE HERE


PICTURE 25.04

PHOTOGRAPHIC EVIDENCE

26.00 MBUSI VS30 SCR TANT HELIUM LEAK TEST ALUMINUM TEST CAP PLUG AND RUBBER INSERTS RENEW - Worn out and or missing need X4 aluminum cap and X24 rubber insert bungs



PICTURE 26.01



PICTURE 26.02

INSERT PICTURE HERE


PICTURE 26.03

INSERT PICTURE HERE


PICTURE 26.04

PHOTOGRAPHIC EVIDENCE

27.00 REPLACE ALL WORN TOOLING ON BR167 UPPER SHELL ASSEMBLY - Most of the tooling to tooling and part to tooling fixture are worn out and or broken and need to be replaced.




PICTURE 27.01



PICTURE 27.02




PICTURE 27.03




PICTURE 27.04

PHOTOGRAPHIC EVIDENCE

28.00 REPLACE ALL WORN TOOLING ON BR167 UPPER SHELL ASSEMBLY - Most of the tooling to tooling and part to tooling fixture are worn out and or broken and need to be replaced.



PICTURE 28.01




PICTURE 28.02

PICTURE 28.03

PICTURE 28.04

PHOTOGRAPHIC EVIDENCE

29.00 REPLACE BROKEN MISSING TOWEL STATUS LIGHT TOWLER ON UPPER SHELL ASSEMBLY 3017194 - This is necessary so the operator if visually alerted if the part is good (green light) or bad (red light).



(ARROWED) 0220-1730194-2016-155 UPPER SHELL ASSEMBLY STACK LIGHT TOWER)
 REQUESTING TWO (2) REPLACEMENT STACK LIGHT TOWERS. THERE ARE TWO MOUNTED INSIDE THE MACHINE ON BOTH SIDES. BOTH ARE DAMAGED AND I WAS UNABLE TO DETERMINE THE MANUFACTURER'S NAME OR ANY DETAILS ABOUT HOW MANY LIGHTS AND COLORS WERE ON THE STACK TOWER. I HOPE MAYBE YOU HAVE A RECORD OF WHAT YOU INSTALLED ON HERE.

PICTURE 29.01



PICTURE 29.02




PICTURE 29.03



PICTURE 29.04


PHOTOGRAPHIC EVIDENCE

30.00 3017193 SHELL TO SHELL WELDER REPLACE BROKEN OR MISSING LOCKING PAWLS, CABLE CLIPS 3017194 - A lot of the locking hooks are missing and broken on the loading table fixtures for both VS30 and BR167




(ARROWED) MBUSI BR167 LOCKING FINGER TOOL (SX SIDE)
 I AM REQUESTING X12 OF MBUSI BR167 LOCKING FINGER TOOL. THIS IS AN ATTACHMENT THAT IS MOUNTED TO THE END OF THE PNEUMATICALLY ACTUATED CLAMPING MECHANISM THAT HOLD THE SHELL IN PLACE IN THE LOADING TABLE FIXTURE.

PICTURE 30.01




(ARROWED) PLASTIC FLEX CORRUGATED ELECT. CABLE PNEU. TUBE LOOM MOUNTING CLIP - 29 MM (DX SIDE)
 I AM REQUESTING X12 OF THESE MOUNTING CLIPS OR CLAMPS USED FOR SECURING FLEXIBLE CORRUGATED PLASTIC LOOM CONDUIT. IT DOES NOT HAVE THE MANUFACTURER NAME MARKED ON ANY WHERE BUT THE DIAMETER IS MARKED AS Ø 29. WHAT IS MISSING IS THE TOP PART OF THE CLAMP THAT HOLDS THE FLEX TUBE IN PLACE.

PICTURE 30.02



(ARROWED) PLASTIC FLEX CORRUGATED ELECT. CABLE PNEU. TUBE LOOM MOUNTING CLIP - 17 MM (DX SIDE)
 I AM REQUESTING X12 OF THESE MOUNTING CLIPS OR CLAMPS USED FOR SECURING FLEXIBLE CORRUGATED PLASTIC LOOM CONDUIT. IT DOES NOT HAVE THE MANUFACTURER NAME MARKED ON ANY WHERE BUT THE DIAMETER IS MARKED AS Ø 17. WHAT IS MISSING IS THE TOP PART OF THE CLAMP THAT HOLDS THE FLEX TUBE IN PLACE.

PICTURE 30.03




(ARROWED) 0-170 PSI PRESSURE GAUGE (DX SIDE)
 I AM REQUESTING X06 REPLACEMENT AIR PRESSURE GAUGES FOR THE LOADING TABLE DX SIDE PLATE FOR THE MBUSI VS30 SCR TANK.

PICTURE 30.04

PHOTOGRAPHIC EVIDENCE

31.00 3017213 HELIUM LEAK TESTER FIXTURES AND FITTINGS REPLACEMENTS FOR VS30 AND BR167 - A lot of the locking hooks are missing and broken on the loading table fixtures for both VS30 and BR167

LOCATING LOCKING PLUNGER PINS



(ARROWED) HELIUM LEAK TESTER DETENT LOCATOR (SPRING LOADED PLUNGER PIN)
 I AM REQUESTING X4 REPLACEMENT HELIUM LEAK TESTER LOCATOR (SPRING LOADED PLUNGER PINS). THESE ARE MOUNTED ON EACH OF THE SLIDING FIXTURES FOR ALL THE SCR TANKS (SLIDING TABLES). THIS SPRING LOADED PLUNGER PIN IS PULLED UP BY THE OPERATOR. THE SLIDING TABLE FIXTURE IS SLID INTO THE TESTING CHAMBER AND THE PIN IS RELEASED LOCKING IT INTO THE DETENT LOCATOR TO HOLD THE FIXTURE TABLE IN PLACE DURING TESTING. AS THIS IS MOUNTED TO THE FIXTURE TABLE I AM CLASSIFYING THIS PART UNDER A FIXTURE. SPARE PART

PICTURE 31.01

REPLACE ALL BROKEN PIN & SLEEVE CONNECTOR BLOCKS



(ARROWED) HELIUM LEAK TESTER MULTI PIN ELECTRICAL LATCHING CONNECTOR (PLUG AND RECEPTACLE)
 I AM REQUESTING X10 REPLACEMENT HELIUM LEAK TESTER MULTI PIN ELECTRICAL LATCHING CONNECTOR PLUGS. AS THIS CONNECTS THE ELECTRICS FROM THE FIXTURE TO THE MACHINE. I AM CLASSIFYING THIS PART UNDER A FIXTURE. SPARE PART. I CANNOT MAKE OUT WHO THE MANUFACTURER IS AND ALMOST CERTAINLY A EUROPEAN MADE. WHAT HAS HAPPENED TO MANY OF THE CONNECTORS IS THAT THE LATCHING CLIPS HAVE BROKEN MAKING DIFFICULT FOR THE OPERATOR TO LATCH THE CONNECTOR IN PLACE. I AM ONLY REQUESTING THE RECEPTACLES BUT IF IT HAS TO COME WITH THE PLUG, I WILL HAVE TO PURCHASE THOSE TOO AS A SET IF NEED BE.

PICTURE 31.02

RESTORE ORIGINAL TAPER PLUG FOR VS30



(ARROWED) HELIUM LEAK TESTER MBUSI VS30 SCR TANK PLUG)
 I AM REQUESTING X6 REPLACEMENT HELIUM LEAK TESTER MBUSI VS30 SCR TANK TAPER PLUG. THIS PLUG IS USED TO PLUG OR BLANK OFF THE SO CALLED "VALVE" LOW FLOW WITH MEMBRANE DURING HELIUM LEAK TESTING. I AM SURE THIS M6 X 45 MM ALLEN CAP SCREW THAT LOOKS LIKE IT HAS BEEN TURNED DOWN ON THE END FOR A MAKE SHIT PLUG CAN NOT BE THE ORIGINAL DESIGN. PLEASE COULD YOU CHECK YOUR RECORDS OF WHAT THE ORIGINAL DESIGN WAS AND SEND THOSE TO ME.

PICTURE 31.03

REPLACE ALLUMINUM RUBBER INSERT PLUG BUNG VS30




(ARROWED) HELIUM LEAK TESTER MBUSI VS30 SCR TANK CAP (PLUG)
 I AM REQUESTING X6 REPLACEMENT HELIUM LEAK TESTER MBUSI VS30 SCR TANK CAP (PLUG). THIS PLUG IS USED TO PLUG OR BLANK OFF A BARB FITTING ON THE SCR TANK DURING HELIUM LEAK TESTING. IF THIS IS A THREE (3) PART COMPONENT OF THE ALUMINUM CAP, SNAP RING (CIRCLIP) AND RUBBER PLUG OR BUNG PLUG THEN I WOULD LIKE TO HAVE SIX (6) OF EACH.

PICTURE 31.04

PHOTOGRAPHIC EVIDENCE

32.00 3017213 HELIUM LEAK TESTER FIXTURES AND FITTINGS REPLACEMENTS FOR VS30 AND BR167 - A lot of the locking hooks are missing and broken on the loading table fixtures for both VS30 and BR167


REPLACE LH AND RH PUMP CAP SEAL CLAMP



(ARROWED) HELIUM LEAK TESTER MBUSI VS30 SCR TANK TOGGLE CLAMP
I AM REQUESTING X4 REPLACEMENT HELIUM LEAK TESTER MBUSI VS30 SCR TANK TOGGLE CLAMP. THIS TOGGLE CLAMP IS USED TO SECURE THE SCR IN PLACE DURING HELIUM LEAK TESTING.

PICTURE 32.01

REPLACE SUPPORT POST FOR VS30 FIXTURE



(ARROWED) HELIUM LEAK TESTER MBUSI VS30 SCR TANK NYLON SUPPORT POST
I AM REQUESTING X8 REPLACEMENT HELIUM LEAK TESTER MBUSI VS30 SCR TANK NYLON SUPPORT POST. THE BOTTOM OF THE SCR TANK ON TWO THESE NYLON SUPPORT POST SOME ARE MISSING OR BROKEN, REQUESTING THE NYLON POST ONLY.

PICTURE 32.02

REPLACE WORN TAPER PLUG BR167



(ARROWED) MBUSI BR167 SCR TANK VENT PIPE TAPER PLUG
I AM REQUESTING X4 REPLACEMENT SCR TANK VENT PIPE PLUG USED DURING LEAK TESTING IN THE HELIUM LEAK TESTERS. ORIGINALS HAVE BECOME WORN AND SCORED ON THE TAPERED SURFACE AFFECTING PROPER SEALING.

PICTURE 32.03

REPLACE ALL MISSING AND BROKEN FLEX CONDUIT CLIPS




(ARROWED) BMW G95/G96/G97 SCR TANK HELIUM LEAK TESTER FIXTURE. PLASTIC CONDUIT SNAP IN PLACE CLAMP
I AM REQUESTING X12 REPLACEMENT PLASTIC CONDUIT SNAP IN PLACE CLAMPS. I AM USING THE FIXTURE REFERENCE AS A GUIDE FOR YOU TO IDENTIFY WHICH MANUFACTURER OF CLAMP YOU USED FOR THIS FIXTURE. THERE IS NO MANUFACTURER MARKED ON IT BUT THE SPEC IS AS FOLLOWS:

PICTURE 32.04

PHOTOGRAPHIC EVIDENCE

33.00 3017213 HELIUM LEAK TESTER FIXTURES AND FITTINGS REPLACEMENTS MACHINE - Replacement parts and components for the helium leak tester


REPLACE DAMAGED BENT FRONT COVER ON BOTH SIDES



(ARROWED) HELIUM LEAK TESTER FRONT MACHINE FRAME COVER GUARD
I AM REQUESTING X2 REPLACEMENT HELIUM LEAK TESTER MACHINE FRAME COVER GUARDS. THE ORIGINALS HAVE BECOME DAMAGED BY THE CARELESS PLACING OF OBJECTS ON THE SURFACE IN WHICH THE CHAMBER DOOR CRUSHES DOWN UPON.

PICTURE 33.01

REPLACE WORN OUT LOCKING FIXTURE PIN DETENT BOTH SIDES



(ARROWED) HELIUM LEAK TESTER DETENT LOCATOR FOR LOCKING IN POSITION SLIDING TABLE
I AM REQUESTING X4 REPLACEMENT HELIUM LEAK TESTER DETENT LOCATOR TOOL FIXTURE FOR LOCKING IN PLACE INSIDE OF HELIUM TESTER CHAMBER SLIDING TABLE FIXTURE. THIS IS A LOCATOR FOR THE SPRING LOADED PIN PLUNGER FOR HOLDING THE SLIDING FIXTURE TABLE INSIDE THE CHAMBER DURING TESTING. ALTHOUGH MBUSI VS30 SCR TANK WAS RUNNING AT THE TIME THAT I TOOK THIS PICTURE THIS IS MOUNTED TO THE MACHINE ITSELF SO I AM CLASSIFYING THIS PART UNDER A MACHINE SPARE PART.

PICTURE 33.02

REPLACE BOTH DEFECTIVE DOOR CONTROL VALVES



(ARROWED) HELIUM LEAK TESTER DOOR AIR CYLINDER PILOT CONTROLLED CHECK VALVE
I AM REQUESTING X4 PILOT CONTROLLED CHECK VALVES OR AIR CYLINDER CONTROL VALVES. THESE ARE MADE BY FESTO AND THE PART NUMBER IS HCL-12-05-12 (330949)

PICTURE 33.03

REPLACE BROKEN DISCONNECT HANDLE ON MAIN PANEL BOARD




(ARROWED) HELIUM LEAK TESTER MAIN ELECTRICAL PANEL DISCONNECTOR LEVER
I AM REQUESTING X1 MAIN ELECTRICAL CONTROL PANEL DISCONNECTOR LEVER. IF THIS MEANS HAVING TO PURCHASE THE WHOLE SWITCHGEAR MECHANISM SO BE IT.

PICTURE 33.04

PHOTOGRAPHIC EVIDENCE

34.00 3017195 END OF LINE TESTER - Replacement parts and components for the end of line tester fixture and fitting and machine.


PUMP MODULE TEST RECEPTACLE BUSHINGS BR67



(ARROWED) BMW G95/G96/G97 SCR TANK PUMP MODULE TESTER HEAD PLUG RUBBER GROMMET BUSHING
I AM REQUESTING X12 BMW G95/G96/G97 SCR TANK PUMP MODULE TESTER HEAD PLUG RUBBER GROMMET BUSHINGS. IN THE PICTURE THE GROMMET BUSHING IS MISSING AND I AM RELYING ON YOUR RECORD KEEPING AS TO WHAT TYPE OF RUBBER BUSHING YOU USED FOR THIS AND IT DIMENSIONS.

PICTURE 34.01


REPLACE BENT DUST CAP DETECTION PROX BRACKET MOUNT



(ARROWED) MBUSI BR167 SCR TANK FILLER NECK INSERT SLEEVE PROXIMITY SENSOR MOUNTING BRACKET
I AM REQUESTING X2 FILLER NECK INSERT SLEEVE PROXIMITY SENSOR MOUNTING BRACKET FOR THE DAMLER BR167 FIXTURE FOR THE END OF LINE TESTER.

PICTURE 34.02

TEST PROBE BLOCKS AND TEST PROBES



(ARROWED) MBUSI BR167 END OF LINE TESTER TEST HEAD SPRING-LOADED SCREW-IN TEST PROBES
REQUESTING X48 REPLACEMENT TEST HEAD SPRING LOADED SCREW-IN TEST PROBES. TO ILLUSTRATE I HAVE IMPOSED A PICTURE OF TEST BLOCK 2 SPRING-LOADED SCREW-IN TEST PROBE. THE TEST PROBE HEAD TYPE IS BERRATED.

PICTURE 34.03

REPLACEMENT SILICONE BUSHING FOR TEST HEAD BR167



PICTURE 34.04

PHOTOGRAPHIC EVIDENCE

36.00 3017195 END OF LINE TESTER - Replacement parts and components for the end of line tester fixture and fitting and machine.

VS30 #30 BUSHING FORK ALIGNMENT REPLACEMENT UPGRADE



PICTURE 36.01

REPLACEMENT BUSHING CONVEYOR FEED VIBRATER MODULE



PICTURE 36.02


PICTURE 36.03

PICTURE 36.04

PHOTOGRAPHIC EVIDENCE

37.00 3017194 UPPER SHELL ASSEMBLY BR167 TOOLING - Additional tooling replacement because of being worn or damaged.

BR167



PICTURE 37.01

BR167



PICTURE 37.02

BR167



PICTURE 37.03

BR167



PICTURE 37.04

PHOTOGRAPHIC EVIDENCE

38.00 3017192 PUMP TO SHELL WELDER FIXTURES BR167 AND VS20 - Additional tools and part replacement



(ARROWED) MULTI-PIN LOCKING PLUG AND RECEPTACLE CONNECTOR
 I AM REQUESTING X 3 MULTI-PIN LOCKING PLUG AND RECEPTACLE CONNECTOR. THIS PLUGS INTO THE SECOND STATION FIXTURE. THE LOCKING LEVERS HAVE BECOME BROKEN AND HAVE FALLEN OFF AND BECOMES UNPLUGGED.

PICTURE 388.01













PICTURE 38.02













PICTURE 38.03




PICTURE 38.04



PHOTOGRAPHIC EVIDENCE


6 Ws 2 Hs 6 Ms

| | | | | | | | | | | | |
|---|---|--|--|--|---|--|---|--|---|---|--|
|  Fishbone Diagram |  Work Breakdown Structure |  Problem Statement Agreement |  5 Ms |  5 Whys Worksheet - Manpower |  5 Whys Worksheet - Machine |  Problem Solving Worksheet |  Lean Continuous Improvement Glossary Quins |  Problem Statement Agreement |  PFMEA Criteria |  Brainstorming Strategies |  5 Whys 2 Hows Explanation |
|---|---|--|--|--|---|--|---|--|---|---|--|

| | | | | | | | | | | | |
|---|---|---|--|---|---|---|---|---|---|---|--|
|  Kaizen Definitions |  5 Ms 2 Hs 6 Ws |  Kaizen Event Planning Scheduling |  Kaizen Checklist |  Waste Walk Observation Data Collection Sheet |  Six Sigma DMAIC Checklist - Define |  Document |  Document |  Document |  Document |  Document |  What Is Six Sigma |
|---|---|---|--|---|---|---|---|---|---|---|--|

| | | | | | | | | | | | |
|--|---|--|--|--|--|--|--|--|--|--|--|
|  |  13 Steps to Create a Value Stream Map |  Document | | | | | | | | | |
|--|---|--|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | | | |
|--|---|--|--|--|--|--|--|--|--|--|--|
|  1-Normality Test - Anderson-Darling |  Basic Statistics | | | | | | | | | | |
|--|---|--|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|--|--|
|  Single Point Lesson - Single Cycling 2300C. Injection | | | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|--|--|